

To: [Scott Authorised Distributors & Authorised Service Centres]

From: Kevin McComb, Technical Manager, Scott Health & Safety

Date: 24 January 2011.

Subject: Important Safety Notice regarding Scott ELSA emergency escape.

Scott Health & Safety Australia, New Zealand has identified a potential for some ELSA 10 & 15 minute escape sets to lose pressure through the gauge and become in-operable.

The affected goods were purchased between September 8th 2010 and December 6th 2010:

- ELSA 10 minute stock code 2009412
- ELSA 15 minute stock code 2009419

Specific units that may be affected have been identified and those that have not already been located and rectified are listed below by reference to each unit's reducer, cylinder and hood number.

Scott Health & Safety requests that you urgently check any installed ELSA 10 & 15 minute escape sets against the numbers listed below, so that these units can be promptly located and repaired. Reducer serial numbers are marked on the bag and reducer Hood numbers and cylinder numbers are marked accordingly:

	Reducer No	10 Minute Cyl No	Hood No
1	0510025246	TGD 097	LT76 270
2	0710028636	TGD 154	LT75 805
3	0710028653	TGD 167	LT75 799
4	0710028654	TGD 072	LT7 6268
5	0710028667	TGD 066	LT7 5607
6	0710028675	TGD 039	LT7 5404

	Reducer No	15 Minute Cyl No	Hood No
1	0710028377	TJD 091	LT7 6524

Please respond to the below signatory at your earliest convenience to confirm:

1. that you have checked all installed units; and
2. whether or not you have located one of the listed affected ELSA units.

If you have installed an affected ELSA unit please immediately remove it from service and contact me to arrange for it to be replaced free of charge.

Regards
Kevin



Kevin McComb
Technical Manager ANZ
Scott Health & Safety